

! " # ! \$ % " & ! " ' (

230-DF-3871-A-005-A	Hallway (B-44)	05/25/2021	05/27/2021	A1E0984-01	Lead	ND	0.2	15	ppb
230-DF-3904-A-005-A	Hallway (148)	05/25/2021	05/27/2021	A1E0984-02	Lead	ND	0.2	15	ppb
230-DF-3895-A-005-A	Hallway (13)	05/25/2021	05/27/2021	A1E0984-03	Lead	0.292	0.2	15	ppb
230-DF-3912-A-005-A	Hallway (131)	05/25/2021	05/2 /2021	A1E0984-04	Lead	0.23	0.2	15	ppb
230-DF-3897-A-005-A	! a"e#\$%&' (05/25/2021	05/27/2021	A1E0984-05	Lead	ND	0.2	15	ppb
230-DF-389 -A-005-A	Hallway (201)	05/25/2021	05/27/2021	A1E0984-0	Lead	ND	0.2	15	ppb
230-DF-3889-A-005-A	Hallway (103)	05/25/2021	05/27/2021	A1E0984-07	Lead	ND	0.2	15	ppb
230-DF-3891-A-005-A	Hallway (110)	05/25/2021	05/27/2021	A1E0984-08	Lead	ND	0.2	15	ppb
230-DF-5822-NA-005-A)#*+e,	05/25/2021	05/27/2021	A1E0984-09	Lead	ND	0.2	15	ppb
230-DF-5823-NA-005-A	Heal#+ -\$\$ (05/25/2021	05/2 /2021	A1E0984-10	Lead	0.772	0.2	15	ppb