

Area B2 seismic upgrades are wrapping up here soon. MEP/F system overhead rough-in is in progress with existing floor finishes in process. Interior wall framing is occurring on all floors. Fire rated ceiling metal framing followed by sheetrock is in process this month. The Area B2 Commons roofing is occurring this month followed along with installation of the MEP/F overhead rough-in. Many interior finish

ROOSEVELT MODERNIZATION

March 2017

